$3 \times 10 = 30$ 



### 6446

## **BOARD DIPLOMA EXAMINATION, (C-16)**

# MARCH / APRIL — 2021

### DME — FOURTH SEMESTER EXAMINATION

#### **ENGINEERING MATERIALS**

Time: Three Hours] [Maximum Marks: 80

PART-A

**Instructions:** 

- (i) Answer all questions.
- (ii) Each question carries three marks.
- (iii) Answers should be brief and straight to the point and shall not exceed *five* simple sentences.
- 1. Distinguish between Destructive and Non-destructive tests.
- 2. Define Space lattice and a Unit cell.
- 3. What are the main raw materials used for production of iron?
- 4. Calculate the percentage of Cementite and Pearlite in 1.2% carbon steel.
- 5. What is Thermal equilibrium diagram?
- 6. List out any six methods of heat treatment of steel.
- Differentiate between Annealing and Normalizing.
- **8.** List out the different types of cast iron.
- **9.** Write the composition, properties and uses of Duralumin.
- 10. State the different methods of producing metal powders.

/6446 1 [ Contd...

**PART-B**  $10 \times 5 = 50$ 

11.	Exp	plain Ultrasonic testing with a neat sketch.	5+5
12.		at are the factors promoting the grain size? What is the effect of grain smechanical properties?  Scribe the L-D converter with a neat sketch.  Explain cooling curve of pure iron.	size 5+5
13.	Des	scribe the L-D converter with a neat sketch.	5+5
14.	(a)	Explain cooling curve of pure iron.	4
	( <i>b</i> )	Distinguish between Hypoeutectoid, eutectoid, Hypereutectoid steels.	2+2+1
15.	Exp	plain the following processes:	4+3+3
	(a)	Carburising	
	(b)	Nitriding	
	(c)	Sub-zero treatment	
16.	Stat	plain the following processes:  Carburising  Nitriding  Sub-zero treatment  te the influence of the following elements on plain carbon steels:	2.5×4
	(a)	Silicon	
	( <i>b</i> )	Manganese	
	(c)	te the influence of the following elements on plain carbon steels:  Silicon  Manganese  Phosphorus  Sulphur	
	( <i>d</i> )	Sulphur	
17.	(a)	Define the following properties:	2+2
		(i) Toughness	
	1/2	(ii) Impact strength	
1	(b)	State the properties and uses of	
		(i) copper	
		(ii) zinc	
		(iii) Lead.	2+2+2
		V/	= · <b>-</b>

**Instructions:** 

(i) Answer any **five** questions.

(ii) Each question carries ten marks.

(iii) Answers should be comprehensive and the criterion for valuation is the content but not the length of the answer.

/6446 2 [ Contd...

- (a) Rolling
- (b) Explosive compacting
- A.A.M.M. & V.V.R.S.R. POLYTEINIC, GUDLAVALLERU, KRESHNA DIST, A.P. (c) Slip casting

/6446 3 AA21—PDF